



NOTES:

1. FOR WIRING DIAGRAM, SEE FIGURE 2-13.
2. RESISTOR VALUES ARE IN OHMS.
3. CONNECTORS ARE VIEWED FROM CONTACT SIDE.

Figure 2-12. Control Unit, Schematic Diagram